

Case 1 ..... 1  
    AddInfo ..... 1  
    Cause ..... 1  
    Solution ..... 1  
Case 2 ..... 1  
    AddInfo ..... 1  
    Cause ..... 1  
    Solution ..... 1

ethercat, , homing, -21070, ,

# Error : -21070

× -21070 (Homming Start Timeout)

## Case 1

**AddInfo**

- (-) 가
- (-) ( NOT )
- -21070 (Homming Start Timeout) 가

**Cause**

- POT 가 (+)

**Solution**

- POT OFF

## Case 2

**AddInfo**

- 가
- , -21070 (Homming Start Timeout) 가
- 

**Cause**

- SDO 0x6080 (Max motor speed) 0 <sup>1)</sup>

**Solution**

- SDO 0x6080 3000

- ecmSxCfg\_SetMaxSpdOfCT() MaxSpd 3000 <sup>2)</sup>
- <sup>3)</sup>

<sup>1)</sup>

Omron 0x607F (Max Profile Speed)

<sup>2)</sup>

Omron 0x607F ecmSxCfg\_SetMaxProfSpdOfCT()

<sup>3)</sup>

100

From:

<http://comizoa.co.kr/info/> - -

Permanent link:

[http://comizoa.co.kr/info/doku.php?id=platform:ethercat:100\\_api:5\\_errorcode:21070&rev=1544503471](http://comizoa.co.kr/info/doku.php?id=platform:ethercat:100_api:5_errorcode:21070&rev=1544503471)

Last update: **2024/07/08 18:22**