


가	가		1
가			2

ETS-DO

X



'OFF'

- No.1 OFF :
 - ETS-DO16 : Ch.0 ~ Ch.7
 - ETS-DO32 : Ch.16 ~ Ch.31
- No.1 ON :
 - ETS-DO16 : Ch.0 ~ Ch.7
 - ETS-DO32 : Ch.16 ~ Ch.31
- No.2 OFF :
 - ETS-DO16 : Ch.8 ~ Ch.15
 - ETS-DO32 : Ch.0 ~ Ch.15
- No.2 ON :
 - ETS-DO16 : Ch.8 ~ Ch.15
 - ETS-DO32 : Ch.0 ~ Ch.15

가

- ComiIDE 1.5.1.3 , ESI
 - **COMIZOA-ETS**
 - , “COMIZOA_ET.S.xml” ..\ComiIDE\Data\XML“

- **Slaves** **EEPROM Update**

Slave RW

[02FF] MASTER-DC

EtherCAT

Net 0

00 : [02FF] MASTER-DC

01 : [020B] ETS-DO16N-E

Index Order

ID Order

InfoEEPROMCoE SDORegisterUpdate


Load

Read


Update

No	Register	Value	Current
☒ 0x0	PDI Control		0x0504
☒ 0x1	PDI Configuration		0x0E00
☒ 0x2	Pulse length Sync signals		0x2710
☒ 0x3	Extended PDI Configuration		0x0000
☒ 0x8	Vendor ID		0xAAAAAA...
☒ 0xA	Product Code		0x5132AA00
☒ 0xC	Revision No		0x14111001

- 1) **Update** - 2) - 3) **Load** Module List



• COMIZOA → **ETS-DO16N-E-LD** , Select



- Update

- Slaves

EEPROM Update

Slave RW

[02FF] MASTER-DC

EtherCAT

Net 0

00 : [02FF] MASTER-DC

01 : [020B] ETS-DO16N-E

Index Order

ID Order

InfoEEPROMCoE SDORegisterUpdate


Load

Read


Update

No	Register	Value	Current
☒ 0x0	PDI Control		0x0504
☒ 0x1	PDI Configuration		0x0E00
☒ 0x2	Pulse length Sync signals		0x2710
☒ 0x3	Extended PDI Configuration		0x0000
☒ 0x8	Vendor ID		0xAAAAAA...
☒ 0xA	Product Code		0x5132AA00
☒ 0xC	Revision No		0x14111001

- 1) Update
- 2)
- 3) Load
- Module List



• COMIZOA → **ETS-DO16N-E** , **Select**





• Update

×

'-LD' 'Latch Disable'

'-LD' 가 EEPROM Update

× **Warning!**

[ethercat](#), [ets](#),

From:

<http://comizoa.co.kr/info/> - -

Permanent link:

http://comizoa.co.kr/info/doku.php?id=platform:ethercat:70_users_guide:20_ts:ets_do_ld&rev=1611749470

Last update:

2024/07/08 18:22