

# Table of Contents

<b>Case 1</b> .....	1
Solution .....	1

# LS MECAPION : SafeOP 전환 실패

× LS MECAPION Driver 연결 시 PreOP → SafeOP 전환이 안됨.

## Case 1

home Cause 

- XML <sup>1)</sup>에서 SM2, SM3의 Enable="0"으로 되어 있음

### Solution

- Enable="1"로 변경

1)

LS Mecapion L7N\_V0.03e.xml

From:

<http://comizoa.co.kr/info/> - -

Permanent link:

[http://comizoa.co.kr/info/doku.php?id=platform:ethercat:70\\_users\\_guide:20\\_ts:ls\\_safeop\\_failed&rev=1540444231](http://comizoa.co.kr/info/doku.php?id=platform:ethercat:70_users_guide:20_ts:ls_safeop_failed&rev=1540444231)

Last update: **2024/07/08 18:22**