

Case 1 1
Cause 1
Add Info 1
Solution 1

ethercat, , panasonic, , , 80.6, alarm, error, noise, jitter, lostframe

PANASONIC : Alarm 80.6

x 80.6 .

Case 1

Cause

- SyncMode 가 SM2 Event Mode , Jitter LostFrame

Add Info

- ?
- PLL (Phase-Locked Loop) :
- PLL
 - 가 ()
 - Driver IRQ Source() 가

Solution

- SyncMode 가 SM2 Event Mode , DC Sync Mode

From: <http://comizoa.co.kr/info/> - -

Permanent link: http://comizoa.co.kr/info/doku.php?id=platform:ethercat:70_users_guide:20_ts:panasonic_alarm_80.6

Last update: 2024/07/08 18:23