

	1
Case 1	1
Cause	1
Solution	1
Case 2	1
Cause	1
Solution	2

× Limit(EL) 가

Case 1

Cause

- EL “ ”
- EL 가 가

Solution

- EL “ ”

The screenshot shows the 'AxisList' window with 'Axis 0' selected. The 'Setup' tab is active, displaying a list of parameters for Axis 0. The 'EL Stop Mode' is set to 'Immediate' and is highlighted with a red box. The 'Inposition Enable' is also set to 'Immediate'. The 'Speed Mode' is set to 'S-CURVE'. The 'Work Speed' is 10000, 'Acceleration' is 100000, 'Deceleration' is 100000, 'Initial Speed' is 100, 'Max Speed' is 655350, and 'Min Speed' is 10. A slider for '100 %' is also visible.

Case 2

Cause

- 가
- 가 Feedback Command

Command Position

Solution

-

From:
<http://comizoa.co.kr/info/> - -

Permanent link:
http://comizoa.co.kr/info/faq:motion:common:03_el_not_stop_imm

Last update: 2021/06/07 14:56