


Check 1

Feature Introduction

x ServoTunes



1 AxisList

- LoadOne / SaveOne / ReadOne One
- LoadAll / SaveAll / ReadAll All

Check

[2] Axis 4

[0] COMI-LX554 (EtherCAT)

Axis 0 (PANASONIC_A5B)

Axis 1 (PANASONIC_A5B)

Axis 4 (PANASONIC_A5B)

Axis 5 (PANASONIC_A5B)

Axis 6 (FASTECH)

Axis 7 (FASTECH)

• ReadAll “Axis 0”

• ReadOne “Axis 4”

2 Category

- Category

- Category

3 Parameter List

- Minimum : 가
- Maximum : 가
- Default :
- Servo :**
- Value : ServoTunes**
 - 'Servo' Write
 - Value cell

4 Search Param

5 10 6 16

- 10 16 .
- Minimum, Maximum, Default, Servo, Value

7 Param Reset

- 'Servo' / 'Value'
- , Read

8 View Details

- Index, DataType, DataSize

9 LoadOne 10 LoadAll

- 2) 가
- ex) Omron / Panasonic

```
11 SaveOne 12 SaveAll
```

- Read

13 CompareToAxis

14 CompareToFile

- SaveOne .

15 ReadOne 16 ReadAll

-
- Load 'Value' 'Servo' .

17 WriteOne

- Value 3)

18 Write 1:N

- Value .
- 가 가 .

19 Write N:N

- Value .

20 EepOne 21 EepAll

- 가 EEPROM .

× **Warning!** ServoTunes .

1) .

2) .

ServoTunes 가

3) .

From:
<http://comizoa.co.kr/info/> - -

Permanent link:
http://comizoa.co.kr/info/doku.php?id=application:comiide:tool:servotunes:10_feature_introduction&rev=1541658975

Last update: 2024/07/08 18:23