


Check 1

Feature Introduction

x ServoTunes



1 AxisList

- LoadOne / SaveOne / ReadOne One
- LoadAll / SaveAll / ReadAll All

Check

[2] Axis 4

[0] COMI-LX554 (EtherCAT)

Axis 0 (PANASONIC_A5B)

Axis 1 (PANASONIC_A5B)

Axis 4 (PANASONIC_A5B)

Axis 5 (PANASONIC_A5B)

Axis 6 (FASTECH)

Axis 7 (FASTECH)

• ReadAll “Axis 0”

• ReadOne “Axis 4”

2 Category

- Category

- Category .

3 Parameter List

- - Minimum : 가 .
 - Maximum : 가 .
 - Default : 1)
 - **Servo :** .
 - **Value : ServoTunes**
 - 'Servo' Write .
 - Value cell .

4 Search Param

- .

5 10 6 16

- 10 16 .
- Minimum, Maximum, Default, Servo, Value .

7 Param Reset

- 'Servo' / 'Value' .
- , Read .

8 View Details

- Index, DataType, DataSize .

9 LoadOne 10 LoadAll

- 2)
- 가 .
- ex) Omron / Panasonic

11 SaveOne 12 SaveAll

- .
- Read .

13 CompareToAxis

- .

14 CompareToFile

- SaveOne .

15 ReadOne 16 ReadAll

-
- Load 'Value' 'Servo' .

17 WriteOne

- Value 3)

18 Write 1:N

- Value .
- 가 가 .

19 Write N:N

- Value .

20 EepOne 21 EepAll

- 가 EEPROM .

× **Warning!**
ServoTunes

1)

2)

ServoTunes 가

3)

From:
<http://comizoa.co.kr/info/> - -

Permanent link:
http://comizoa.co.kr/info/doku.php?id=application:comiide:tool:servotunes:10_feature_introduction&rev=1541658984

Last update: 2024/07/08 18:23