

목차

Case 1 1

 Solution 1

LS MECAPION : SafeOP 전환 실패

× LS MECAPION Driver 연결 시 PreOP → SafeOP 전환이 안됨.

Case 1

<icon="fa fa-quote-left"> Cause 

- XML ¹⁾에서 SM2, SM3의 Enable="0"으로 되어 있음

Solution

- Enable="1"로 변경

¹⁾

LS Mecapion L7N_V0.03e.xml

From:
<http://comizoa.co.kr/info/> - -

Permanent link:
http://comizoa.co.kr/info/doku.php?id=platform:ethercat:70_users_guide:20_ts:ls_safeop_failed&rev=1540444205

Last update: 2024/07/08 18:22